

**ACURA & HONDA**

Acura &amp; Honda Recalls, Repair &amp; Diagnostic Tips

RECALLS

DIAGNOSTIC TIPS

REPAIR TIPS

LINKS

E-BOOKS

STORE

OEMDTC

HUAWEI P30 | P30 Pro  
Changez les règles de la photographie

Share

## AWD Indicator Is On With DTC C1850-14 – 2012-2014 Honda CR-V

oemdtc July 14, 2017 Diagnostic Tips



### Download Your eManual Now

Official Repair Manuals Website. Instantly Download Now Online

eManual Online

DOWNLOAD



Organisez votre travail. Gardez le cap. Tenez les délais.

asana

En sa

**A15-012**

February 13, 2015

## AWD Indicator Is On with DTC C1850-14

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2012-14	CR-V	AWD	ALL with AWD



asana



### SYMPTOM

On some 2012-14 CR-V's and in cold weather, the AWD indicator may come on with DTC C1850-14 (low or no torque to the rear wheels).

### CATEGORIES

Select Category 

## 1 Combien vaut ma voiture ?

Calculez la valeur de votre voiture en seulement 1 minute, obtenez la meilleure évaluation [vendezvotrevoiture.fr](http://vendezvotrevoiture.fr)

## 2 Official Car Service Manuals

Official Repair Manuals Website. Instantly Download Now Online eManual Online

### Free Starter Membership

### WEALTHY AFFILIATE

- ✓ Fresh Video, Tutorial, and Courses
- ✓ Get Instant Help & Support
- ✓ Build Websites With Ease
- ✓ Achieve Your Online Business Goals

**SIGN UP NOW**

no credit card required

learn. network. build. succeed.


**POSSIBLE CAUSES**

Over time, moisture and cold weather will cause the AWD [relay](#) to fail.

**CORRECTIVE ACTION**

Replace the AWD [relay](#).


**REQUIRED MATERIALS**

Part Name	Part Number	Quantity
Power <a href="#">Relay</a> Assembly	39794-SDA-A02 	1

**WARRANTY CLAIM INFORMATION**


The normal warranty applies.

Shop Related Products




Wheel and Tire Cleaner - Safe for all Wheels ...

~~\$16.97~~ \$27.97  
(1198)




CP134 (CF10134) Honda & Acura Replacement ...

\$8.87  
(5029)




Genuine Honda 39794-SDA-A05 Power Rela...

~~\$18.64~~ \$18.66  
(126)




Honda Civic & CR-V Haynes Repair Manual

\$20.99  
(145)




PG Air Filter PA5780 | Fits 2007-09 Honda CR-V

\$13.78  
(1)




DNF (1 Pair) 30/40 AMP Relay Harness (Long) SPDT 12V Bosch Style

\$5.50



ONLINE LED STORE 6 Pack - 12V DC 40/30 ...

~~\$12.45~~ \$13.99  
(272)



Cargo Liner Rear Cargo Tray Trunk Floor ...

~~\$71.74~~ \$110.00  
(210)

Ads by Amazon

Operation Number	Description	Flat Rate Time	Template ID	Failed Part Number
7301G0	Replace the AWD <a href="#">relay</a> .	0.6 hr	15-012A	39794-SDA-A03

Defect Code: 03217

Symptom Code: 03272

Skill Level: Repair Technician

**REPAIR PROCEDURE**

1. Find and remove the AWD [relay](#) (for details on how to do this, see the electronic [service manual](#)).

ARCHIVES

Select Month

**High**  
Performance

**SSD**  
Storage

**15**  
Locations




VULTR


Starting from  
**\$5/mo**  
\$0.007/hr

[Get Started](#)

Search ... Search

**Ask a Mechanic Now**

 **Chris (aka- Moose), Technician**  
16 years experience

 **Pearl Wilson, Auto Mechanic's Assistant**  
Welcome! What's going on with your car?

Send

[Donate](#)




Find Key

**Just searched:** what's with cb distillery review, wh distillery review, playstation cash c


NEWSLETTER

**Email address:**

Share



2. Replace the AWD relay.



3. Reinstall the parts in reverse order (see the electronic [service manual](#) for details).

END



February 13, 2015

## AWD Indicator Is On with DTC C1850-14

## AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2012-14	CR-V	AWD	ALL with AWD

## SYMPTOM

On some 2012-14 CR-V's and in cold weather, the AWD indicator may come on with DTC C1850-14 (low or no torque to the rear wheels).

## POSSIBLE CAUSES

Over time, moisture and cold weather will cause the AWD relay to fail

## CORRECTIVE ACTION

Replace the AWD relay.

## REQUIRED MATERIALS

Part Name	Part Number	Quantity
Power Relay Assembly	39794-SDA-A02	1

## WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Template ID	Failed Part Number
7301G0	Replace the AWD relay	0.6 hr	15-012A	39794-SDA-A03

Defect Code: 03217

Symptom Code: 03272

Skill Level: Repair Technician

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

© 2015 American Honda Motor Co., Inc. – All Rights Reserved

Page 1 of 2

[Download \(PDF, 161KB\)](#)

5 Pack - EPAuto 30/40 AMP Relay  
Harness Spdt 12V Bosch Style

List Price: \$12.87

Price: \$12.87

Price Disclaimer

Shares

ONLINE LED STORE 40/30 Amp  
Waterproof Relay Switch Harness Set -  
12V DC 5-Pin SPDT Automotive Relays  
12 AWG Hot Wires

List Price: \$9.99

Price: \$9.99

Price Disclaimer

Beck Arnley 203-0133 Relay

List Price: \$5.13

Price Disclaimer

## 1 Combien vaut ma voiture ?

[>](#)

Calculez la valeur de votre voiture en seulement 1 minute,  
obtenez la meilleure évaluation [vendezvotrevoiture.fr](https://vendezvotrevoiture.fr)



## 2 Download Your eManual Now

Top-Rated Support. Workshop, Repair & Service Manuals  
—Download Now [eManual Online](#)

---

### RELATED POSTS

---

U40 – Driver Frontal

O41 – Driver Frontal

Safety Recall:

Air Bag Inflator May  
Explode – 2002-2016  
Acura

Air Bag Inflator May  
Explode – 2001-2014  
Honda

2014-2019 Acura ILX  
Fuel Tank Inspection  
and/or Fuel Tank  
Replacement

Shares

2017-2018 Honda  
Clarity Fuel Cell – Fuel  
Cell Voltage  
Misdetection Safety  
Recall

Safety Recall:  
2015-2017 Honda  
Accord V6 Fuel Pump

Safety Recall:  
2017-2019 Honda  
Ridgeline Fuel Pump  
Cracks or Leak  
Inspection

< Hard Downshift Or Clunk Whe... PDI And New Model Service Inf... >

LEAVE A COMMENT

Your email address will not be published. Required fields are marked \*

Your Comment Here ...

Name\*

Email\*

Website



CAPTCHA Code \*

Post Comment

This site uses Akismet to reduce spam. [Learn how your comment data is processed.](#)

## File a Vehicle Safety Complaint with NHTSA

<https://www-odi.nhtsa.dot.gov/VehicleComplaint/>

Shares

## Join Our Newsletter ✕

Sign up today for free and be the first to get notified on new updates.

**Subscribe Now**

POWERED BY  SUMO

OEMDTC is a participant in the Amazon Services LLC Associates Program, an affiliate advertising program designed to provide a means for us to earn fees by linking to Amazon.com and affiliated sites.

Copyright ©2019 WimplePro by ThemeCountry

[Disclaimer](#) [Privacy Policy](#) [About](#)