



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/01048/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Honda
Name	Civic, CR-V and HR-V
Type / number of model	Civic (e11*2007/46*3633*), CR-V (e6*2007/46*0265*01, e6*2007/46*0265*02), HR-V (e6*2007/46*0158*).
Company recall code	6FE
Production dates	The affected vehicles were manufactured between 2018 and 2019.
OECD Portal Category	77000000 - Automotive
Description	Model codes: Civic (FC1, FK6, FK7, FK8), CR-V (RT5, RT6, RW1, RW2), HR-V (RU1). Countries of production: México, Japan, Turkey and United Kindom.
Country of origin	Mexico
Alert submitted by	Portugal
Counterfeit *	<b>NO</b>
Risk type	Injuries
Technical defect	Due to inappropriate molding conditions, the density of the resin for the low-pressure fuel pump impeller is reduced, causing it to swell and deform by the fuel. Consequently, the impeller interferes with the pump cover and makes the fuel pump inoperative. As a result the engine may stall, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Greece, Ireland, Slovakia, Slovenia
Images	No pictures are available